

From: ["Young, Howard S." <younghs@cdmsmith.com>](mailto:Young,Howard.S.<younghs@cdmsmith.com>)

To: ["Sheldrake, Sean" <sheldrake.sean@epa.gov>](mailto:Sheldrake,Sean.<sheldrake.sean@epa.gov>)

["Zhen, Davis" <Zhen.Davis@epa.gov>](mailto:Zhen.Davis@epa.gov)

CC: ["Scott Coffey" <coffeyse@cdmsmith.com>](mailto:Scott.Coffey@cdmsmith.com)

madi.novak@state.or.us

Sarah.GREENFIELD@state.or.us

["Trump, Julee M." <trumpjm@cdmsmith.com>](mailto:Trump,Julee.M.<trumpjm@cdmsmith.com>)

["Miner, Libby" <minerl@cdmsmith.com>](mailto:Miner,Libby.<minerl@cdmsmith.com>)

["Fox, Mary" <FoxML@cdmsmith.com>](mailto:Fox,Mary.<FoxML@cdmsmith.com>)

Date: 6/29/2018 8:18:44 AM

Subject: Daily report for Thursday 6/28/18 Portland Harbor Pre-RD Investigation - Surface Sediment Sampling on the Cayuse

Attachments: [Daily Status Report_Portland Harbor_20180628_SurfaceSed.docx](#)

Sean and Davis,

Attached is the daily report for Thursday 6/28/18 which includes oversight of the surface sediment sampling on the Cayuse. The other research vessel, the Tieton, that was scheduled for surface sediment sampling today had engine problems before reaching the boat launch and has gone in for repairs.

Note that there was no work performed on Wednesday 6/27/2018 due to a lack of accessible areas (access agreements) in the site area and PreRD Group finalization of the upstream surface sediment sampling FSP.

Please contact me if you have any questions.

Howard S. Young, LG | CDM Smith

14432 SE Eastgate Way, Suite 100 | Bellevue, WA 98007-6493

T: 425.519.8300 | Direct 425.519.8351 | Cell 206.491.4663 | younghs@cdmsmith.com

[com<mailto:younghs@cdmsmith.com>](mailto:younghs@cdmsmith.com) | [www.cdmsmith.com<http://www.cdmsmith.com>](http://www.cdmsmith.com)